Date:

98.12.16

ENGINEERING CHANGE NOTICE

Project No.: 0120 - 637				Checked By:	///
Project Name: EC 120 STEP			Approved By: (proj. manager) Approved By: (management if req'd)		
Released DEO 9121 Rev.	Δ				
Keensed DD	71.				
. Ade	h 7.65	2¢ 1/	W. B. 156 136	step assembly)	to change
THIONAS	1)201	۷ خاک دید.اداری	erb (ecizo	nep assembly	i i i
end plat	te to	Thai	of 206/407/	427 Style en	d plate.
Notification/Acceptance	Affected ✓		Authorization		
QA			JB/KE Discussini week of		
Production	V		98.12=07		
Planning			48.12201		
Marketing +	<u> </u>				
Indianating Actions	Yes	No	Responsible	To happen by:	Complete
Engineering Actions			Responsible	To happen by.	Complete
Jpdate Blue File Jpdate Pink File	+ +	$\frac{\checkmark}{}$		 	
Jodate Pilik File Jodate D-Part Master Binder	171	<u> </u>	K <i>E</i>	98.12.16	KE 98-12-16
Jpdate Grey Project Binder	+>-		1(10-12-14	ZE 94.12.16
Jpdate DEO Binder	1./		10	Tr.	KF 98.12.16
Jpdate Master Document List	 	V/4	••		WE COME TO
Jpdate Drawing Approval Record	 	//*I	(/	17	RE 94.12.16
Notify TCA of Change	 				
Notify FAA of Change	 			<u> </u>	
totily i Art of Ghange	 	Ť			
Notes:	<u>.ll</u> .	L		<u> </u>	<u> </u>
* As per discussion w/ 3	tim . M	nkig	should prepare le	Her to Eurocopter	France
authoring what change	שתנו בשב	house	made to imara	e step down to	eliminate
problems with weld	cracki	เหล	on end platos	Contact ENGIR F	or details/technical ass
	= - •	· /	The provider		before manufacturing
outlining what change problems with weld - All future production	n sho	ruld	use this new	02734 and cap.	EC 120 steps.
- Existing production and	d parts	in 51	tock which alread	ly have old 17260	19-45 and cap
	1			,	9

- Update D2678 IPP to call up people D2734 and plate in place of D2669-45 - Check Wolding Jigs / Drilling Jigs to ensure that they are not affected by this change.

ECN#: